

G33

Windshield washer fluid level sensor

- on windshield washer fluid reservoir, front
- shown from front with left side turn signal/marker light removed